


K3 Pro Infrared Thermometer









High Accuracy



Alarm Function



3 Installation Methods



°C/°F Unit Avaliable



Data output



Technical Data

Method of measurement	Sensitivity sensor distance sensor	Operating mode	Surface mode /body mode / Count mode
Temperature Unit	*C/*F	Surface temperature measurement range	10-50°C
Accuracy	±0.2 (34~45°C)	Range of Body Mode temperature	35-42°C
Measuring distance	5 - 10 cm	Environment temperature	10-40°C
Display	2.8-inch LCD screen	Counting capacity	9999 times
Install Method	Nail hook/bracket fixing	Record temperature data	Support to review 30 sets of data
Power supply	USB /4 AA batteries	Alarm Function	Flash+sound alarm for about 10 seconds
Response time	0.5s	10 signal output	Support(switch signal / pulse signal)
Working band	5um	Body storage	☐ Connect to the computer ☐
Standby time	305	Volume setting	☑ Voice broadcast ☑
Product Size	170*115*140mm	Backlight switch	☑ Standby ☑
Net weight	303g	Upper alarm limit	☑ Whether to support charging ☑

Quick measurement

Fever alarm



